

TABLE 2—(contd.)

Type Designation	Maker or Originator	CV. No. (or nearest in brackets)	Type Designation	Maker or Originator	CV. No. (or nearest in brackets)	Type Designation	Maker or Originator	CV. No. (or nearest in brackets)
VU7A	M.A.P.	CV.1556	WD2	Triotron		Y62	M.O.V.	
VU16A(O)	M.A.P.		WD30	M.O.V.	CV.3810	Y63	M.O.V.	(CV.1103)
VU29	M.A.P.	CV.1029	WD30 (Met.)	M.O.V.		Y64	M.O.V.	
VU33	M.A.P.	CV.1033	WD40	M.O.V.		Y220	Hivac	(CV.1118)
VU39	M.A.P.	CV.1039	WE3A	W. Electric	CV.3812			
VU39A	M.A.P.	CV.1569	WE8A	W. Electric	C.V.3813			
VU64	M.A.P.	CV.1064	WE258B	W. Electric	CV.2594	ZA1	M.O.V.	(CV.1175)
VU71	M.A.P.	CV.1071	WE262B	S.T.C.	(CV.1728)	ZA2	M.O.V.	(CV.1095)
VU71A	M.A.P.		WE368A	W. Electric	CV.710	ZP455	G.E.C./U.S.	CV.2789
VU72	M.A.P.	CV.1072	WL417A	Westinghouse	CV.2642	ZP477(O)	G.E.C./U.S.	CV.914
VU111	M.A.P.	CV.1111	WL532	Westinghouse	CV.2647	ZP527	G.E.C./U.S.	CV.855
VU113	M.A.P.	CV.1113	WX12			ZP579	G.E.C./U.S.	CV.3842
VU120	M.A.P.	CV.1120	W21-4 Pin	M.O.V.	CV.171	ZP584	G.E.C./U.S.	CV.3843
VU120A	G.P.O.	CV.1001	W21-7 Pin	M.O.V.	CV.3804	ZP590	G.E.C./U.S.	CV.3844
VU133	M.A.P.	CV.1133	W30	M.O.V.		Z6G	M.O.V.	
VU133A(O)	M.A.P.	(CV.54)	W30K	M.O.V.	CV.3805	Z14	M.O.V.	
VU134	M.A.P.	CV.1134	W31	M.O.V.	CV.3806	Z21	M.O.V.	
VU504	M.A.P.	CV.1504	W31 (Met.)	M.O.V.		Z21	M.O.V.	CV.3836
VU508	M.A.P.	CV.1508	W42	M.O.V.		Z21 (7 pin)	M.O.V.	CV.3837
VW36	M.A.P.	CV.1036	W63	M.O.V.	(CV.1183)	Z22	M.O.V.	(CV.1727)
VW42	M.A.P.	CV.1042	W213	Triotron		Z62	M.O.V.	(CV.1192)
VW48	M.A.P.	CV.1048				Z63	M.O.V.	
V63	M.A.P.		XGR			Z90	M.O.V.	(CV.1091)
V120	G.P.O.	CV.3762	XGR3		(CV.151)			
V123B		CV.3763	XH1.5	Hivac	CV.3830	<b>0A2 0B2</b>		
V190(O)			XLO	Hivac	(CV.1701)	<b>0A3 0C3</b>		
V226		CV.3765	XL1.5	Hivac	(CV.1720)	0A4G	R.C.A.	CV.752
V248A	M.A.P.		XL2	Hivac	CV.3831	0Z4	R.C.A.	CV.692
V312	Cosmos	CV.3766	XN		(CV.14)	01A	R.C.A.	CV.750
V339		CV.3767	XP	Hivac	(CV.1702)		S.T.C.	
V503	Cosmos	CV.3768	XP1.5	Hivac	(CV.176)	09	Cossor	CV.2725
V625	Hivac	(C.V.93)	XP2	Hivac	CV.3832	09J	Cossor	(CV.1518)
V717	M.A.P.		XP230	Cossor		054V	Mullard	
V817	M.A.P.		XSG2.0	Hivac	CV.3833	0202	Triotron	
V872	Cosmos	(CV.1116)	XW	Hivac	(CV.1703)	1A3	R.C.A.	CV.753
V877		CV.3769	XW2	Hivac	CV.3834	1A4E	Cossor	
V914	Cosmos		X14	M.O.V.		1A4P	R.C.A.	CV.754
V955	Mazda	CV.3770	X21	M.O.V.	CV.3816	1A5G	R.C.A.	CV.755
V955B			X21 (Met.)	M.O.V.	CV.3817	1A5GT	R.C.A.	CV.756
V960	Cosmos		X22	M.O.V.	CV.3818	1A5GT/C	R.C.A.	CV.756
V970		CV.3772	X23	M.O.V.	(CV.1082)	1A6	R.C.A.	CV.757
V1010	Cosmos	CV.3773	X24	M.O.V.	CV.3819	1A6E	Cossor	
V1020	Cosmos	CV.3774	X24 (Met.)	M.O.V.	CV.3820	1A7G	R.C.A.	CV.1800
V1021	Cosmos	CV.3775	X30	M.O.V.		1A7GT/G	R.C.A.	CV.1802
V1023		CV.3776	X31	M.O.V.	CV.3821	1A7VG	Cossor	
V1029	Cosmos	CV.3777	X31 (Met.)	M.O.V.	CV.3822	1B4P	R.C.A.	CV.758
V1101	Cossor	(CV.1361)	X32	M.O.V.		1B5/25S	R.C.A.	CV.759
V1105	Cosmos	CV.3778	X41	M.O.V.	CV.1460	1B7GT	R.C.A.	CV.760
V1111	Mullard	(CV.1127)	X41 (Met.)	M.O.V.	CV.3823	1B22	U.S.A.	CV.761
V1120	Cosmos	(CV.72)	X56	M.O.V.	(CV.1045)	1B24	U.S.A.	CV.725
V1120B	Cosmos	(CV.73)	X61	M.O.V.	(CV.287)	1B27	U.S.A.	CV.713
V1501	Cosmos	CV.3581	X61M	M.O.V.	(CV.281)	1C5EG		
V1507A	M.A.P.	(CV.1504)	X62	M.O.V.		1C5G	S.T.C.	CV.1803
V1901	Cosmos	(CV.1504)	X63	M.O.V.	CV.3825		Cossor	
V1904	Cosmos	(CV.1072)	X64	M.O.V.	(CV.1280)		Ever Ready	
V1906	Cosmos	(CV.20)	X65	M.O.V.	(CV.1193)		Ferranti	
V1907	Cosmos	(CV.1111)	X66	M.O.V.	(CV.1099)		Mullard	
V1910	Cosmos		X71M	M.O.V.			R.C.A.	
V1913	Cosmos	(CV.1508)	X73M	M.O.V.		1C5GT	R.C.A.	CV.1805
V1920	Cosmos	(CV.121)	X61	M.O.V.	(CV.1103)	1C5GT/G	R.C.A.	CV.1805
V1922	Cosmos	(CV.74)						