

| Type Designation | Maker or Originator | CV No. (or nearest in brackets) | Type Designation | Maker or Originator | CV No. (or nearest in brackets) | Type Designation | Maker or Originator | CV No. (or nearest in brackets) |
|------------------|---------------------|---------------------------------|------------------|---------------------|---------------------------------|------------------|---------------------|---------------------------------|
| 01A | USA | CV750 | | | | | | |
| 02DF | STC | | | | | | | |
| 09 | Mullard | (CV2260) | | | | | | |
| 09D | Cossor | CV2725 | | | | | | |
| 09J | Cossor | (CV1596) | | | | | | |
| | Cossor | (CV1518) | | | | | | |
| 090-001483 | Hallicrafter | CV9733 | | | | | | |
| 0241 | Hewlett | CV10613 | | | | | | |
| | Packard | | | | | | | |
| OA2 | USA, STC | CV1832 | | | | | | |
| OA2WA | USA/ | { (CV4020) | | | | | | |
| | Mullard/ | { (CV4100) | | | | | | |
| | EEV | | | | | | | |
| OA3 | USA | (CV3798) | | | | | | |
| OA3/VR75 | USA | (CV3798) | | | | | | |
| | STC | | | | | | | |
| OA4G | USA | CV752 | | | | | | |
| OB2 | USA | CV1833 | | | | | | |
| OB2WA | USA/ | { (CV4028) | | | | | | |
| | Mullard/ | { (CV4101) | | | | | | |
| | EEV | | | | | | | |
| OB3 | USA | CV3799 | | | | | | |
| OB3/VR90 | USA | CV3799 | | | | | | |
| OC3 | USA | (CV686) | | | | | | |
| OC3/VR105 | USA | (CV686) | | | | | | |
| | Cossor | | | | | | | |
| | STC | | | | | | | |
| OD3 | USA | (CV216) | | | | | | |
| OD3/VR150 | USA | (CV216) | | | | | | |
| | Cossor | | | | | | | |
| | STC | | | | | | | |
| OD3W | USA | CV3979 | | | | | | |
| OG3 | Mullard | (CV449) | | | | | | |
| OZ4 | USA | CV692 | | | | | | |
| | STC | | | | | | | |
| | Ferranti | | | | | | | |
| OZ4A | USA | CV517 | | | | | | |
| ½M2-4Z5 | Motorola | CV10521 | | | | | | |
| ½M100Z10 | Motorola | CV9358 | | | | | | |
| 0-4M2-7Z5 | Motorola | CV10204 | | | | | | |
| 0-4M4-3Z5 | Motorola | CV10198 | | | | | | |
| 0-4M5-1Z5 | Motorola | CV10203 | | | | | | |